Radiogram No. 9871u Form 24 for 02/24/05 Stowing hardware for disposal in Progress. Demating УС-21 telemetry connectors from БИТС2-12

GMT	CREW	ACTIVITY
06:00-06:10		Morning inspection
06:10-06:40		Post-sleep
06:40-07:30		BREAKFAST
07:30-07:45		Daily planning conference (S-band)
07:45-08:15		Work prep
08:15-11:20	FE-1 CDR	Stowing hardware for disposal in Progress 351 (with IMS support)
08:15-09:30		
09:30-11:00	CDR	Physical Exercise (RED)
11:00-12:00		Physical Exercise (TVIS)
11:20-12:20	FE-1	Physical exercise (VELO + Force Loader/Cycle 1), day 3
12:05-12:20	CDR	GASMAP HRF: power up
12:20-13:20		LUNCH
13:20-14:20		Install Progress 351 docking mechanism
14:20-14:50	FE-1	СОЖ maintenance
14:20-17:20	CDR	Ground controlled SSRMS motion with the crew monitoring
14:50-15:00	FE-1	On MCC Go Demating telemetry connector
15:00-15:50		Removing YC-21 box from Progress 351
15:50-17:20		Physical Exercise (TVIS) Day 3
17:20-17:25	CDR	Transfer TVIS, RED, and HRM data to MEC.
17:25-17:30	FE-1	On MCC GO ISS O2 repress from Progress 351CpΠK (start)
17:30-18:10		SM and Progress TORU test without commanding Progress Approach & Attitude Control Thrusters [ДПО]
18:10-18:30	CDR	IMS file prep
18:10-18:15	FE-1	PLANTS-2. Data downlink
18:15-18:20		ISS O2 repress from Progress 351CpΠK (terminate)
18:20-18:45		Daily plan review
18:30-18:35	CDR	GASMAP HRF - routine health check power down
18:35-18:55	CDR	Daily plan review
18:45-18:55	FE-1	Report prep
18:55-19:10		Daily planning conference (S-band)
19:10-19:30		Report prep
19:30-20:00		DINNER
20:00-20:30		Daily food prep
20:30-21:30		Pre-sleep
21:30-06:00		SLEEP

Note: See OSTP for references to US activities.

End of Radiogram